




Jobman Job Process Map Example



Jobman Job Process Map Example



Jobman Job Process Map Example




Jobman Job Process Map Example


Job Type: Residential + Painted

Target Lead Time: 38 Days

PRE-PRODUCTION




MANUFACTURING




MACHINING

INSTALLATION



JOB COMPLETE




Jobman Job Process Map Example

Job Type: Residential + Painted + Stone Tops

Target Lead Time: 48 Days

PRE-PRODUCTION



MANUFACTURING




MACHINING



INSTALLATION


JOB COMPLETE



Jobman Job Process Map Example

Job Type: Re-make Work Order

Target Lead Time: 5 Days




Jobman Job Process Map Example


Job Type: Maintenance Work Order

Target Lead Time: 7 Days

PRE-PRODUCTION



MACHINING



INSTALLATION

JOB COMPLETE

